











- |  |  |
|--|--|
| 1. LCD color graphic display (10.4")   | 5. Numerical keypad 0-9<br>(And optional alphanumerical entries)   |
| 2. Function selection keys<br>(current function is shown at screen bottom)   | 6. Enter key (E-key)   |
| 3. Timing signal indicator lights 1 and 2  | 7. Cursor Keys   |
| 4. Operating mode selection with indicator LED:<br>· MAN - mode (manual/set-up)<br>· AUTO 1 - mode (normal shift)<br>· AUTO 2 - mode (after hour shift)<br>· STOP (machine switched off) | 8. Key depressed together with MAN Key to allow changing the sensor timing window.<br>Enter new start value and Press E-Key<br>Enter new end value and Press E-Key |
|  | 9. C-key (Clear/change display mode)   |

- |   |   |
|---|---|
|  Moves back to multi-curve display; switches between single and multi-curve displays. |  Moves to target curves (tool performance)                           |
|  Moves to the part counters   |  Moves to part data memory (store and reload part data)              |
|  Calls-up multi-trending screen   |  Error log (frequency and related down time)                         |
|  Press to adjust trend limits   |  Error log (errors and error curve log)                              |
|  "Snow flake" button freezes current force wave forms                                 |  Moves to the menu and set-up section (service-access code required) |

## 1 Turn On (push button located on rear panel)

The display and the **MAN**-key light up. **IMPAX-SK 4** is ready. Start the machine and check your parts. When okay, start the monitoring mode (Step 2):

## 2 Press AUTO-key

Unit will move into automatic monitoring mode. During the first few machine cycles the monitoring limits (envelopes) will adjust and fine tune.

## 3 Process Failures (machine stops)

In case of process errors (e. g. force errors or counter stops) the machine will be stopped by the **IMPAX-SK 4** (the green AUTO light turns off, the red AUTO light turns on). The display's top line turns red. The error reason and stop time are displayed.

## 4 Re-start after machine stop

### A) If you wish to re-learn new envelope limits after start-up:

- press the **MAN**-key (stop relays are released so machine can be jogged)
- eliminate the cause of the stoppage, re-start the machine and check the parts
- when parts are ok, press **AUTO** again to start a new learn and activate monitoring.


### B) If you wish to continue using the previous envelope limits:

- go straight to **AUTO** from STOP. Eliminate error and restart the machine
- the monitoring mode will restart as soon as the machine runs consistently

## C Set the part counters

- press function key **C** (counter C1 for order size will appear)
- to set count press **C** (the old value turns blue), enter your desired new count
- confirm your entry with **E**. Actual count zeroes, confirm again with **E**
- to switch counter from stop active (✓) to not active (-): press any key
- use the buttons **2**, **3** or **4** to call up the other counters




## S Set Sensitivity (S) and Tolerance (Tol)

- Press  and then a numbered key to move to the desired channel
- to adjust settings press the **C** key (the sensitivity number will turn blue)
- first adjust **sensitivity (S)** setting (1=coarse, 9=fine, 0=channel is off)
- confirm with **E**. The blue box moves over to **tolerance (Tol.)**
- adjust **Tol.** (1-9 allows faults, 0= immediate stop) and confirm with **E**

# IMPAX-SK 4







## Start-Up Screen

## Displays & Operating Screens



Part Data Memory

Target Curve Memory



C → activates the data entry mode

→ advances to the next screen

⏪ 4 1,2.. Press to activate the function