

Machine Performance Analysis using your process monitoring system.




Your benefits:

- chart of machine run time includes stop/go diagram
- get accurate machine efficiency
- view error and down time statistics
- see error frequency and the resulting down time
- reference the error log and stored fault curves to eliminate future problems
- the SKMachinemaster function is available for all of our PC-based models (IMPAX/SK 4, IMPAX/SK 7 and IMPAX/SK bbx) also available as an option for select existing systems.


IMPAX-SK Technologies
1405 Bernard Drive, Unit B-2
Addison, Illinois 60101
Tel (630) 916-7777
Fax (630) 916-7832
Toll Free (800) 272-4784
E-mail: impaxptg@aol.com
Web: www.impaxptg.com

Gather and view relevant machine performance data such as uptime vs. downtime, error frequency, efficiency, etc.




Machine run time chart shows uptime vs. downtime, error frequency, and machine efficiency.

Selectable time frame allows you to reference statistics as far back as 96 hours.



Error statistics show the distribution of stop codes and resulting accumulated down time.



All errors are kept in memory and are available for recall and further analysis.